

NISSAN DIESEL AMERICA, INC.


TECHNICAL BULLETIN TR-26

DATE: November 3, 2009
 MODEL YEAR: 2004 & LATER
 TRANSMISSION MODEL: MLS62 & MLS63
 BULLETIN NUMBER: TR-26
 FILE IN THE TRANSMISSION SECTION OF THE TECHNICAL BULLETIN BINDER

6TH GEAR & HUB CHANGE FOR MLS62 AND MLS63 TRANSMISSIONS

CHANGE NOTICE

To further improve reliability of the MLS62 and MLS63 manual transmissions, the 6th gear and hub have been changed beginning with vehicles produced on or after July 1, 2009. The 6th gear and hub kit are a **direct replacement kit** for all former versions of the 6th gear and hub used in the MLS62 & MLS63 transmissions. The illustration below shows the design change.



PARTS NOTICE

The 6th gear and hub assembly must be replaced together. Individual parts are not available separately.

Part Name	Former	New	Transmission Model
6th Gear Assembly Hub and Sleeve Set	32240-Z5019 32667-Z5005	K32240Z500C	MLS62 & MLS63

WARNING: THESE PARTS ARE NOT INTERCHANGEABLE WITH PREVIOUS PARTS. Mixing with former parts will result in damage to other transmission components or render the transmission inoperative.

THE INFORMATION CONTAINED IN THIS BULLETIN SHOULD NOT BE INTERPRETED AS THE BASIS FOR WARRANTY CLAIMS							
FOR THE INDICATED PERSONNEL BELOW, PLEASE READ, INITIAL, AND ROUTE TO THE FOLLOWING:							
X	SERVICE MANAGER	X	WARRANTY MANAGER	X	SERVICE TECHNICIANS INITIAL BELOW:		
X	PARTS MANAGER	X	SHOP FOREMAN				